

DAFTAR PUSTAKA

- [BSN] Badan Standardisasi Nasional. (2019). SNI 1726-2019 Tata Cara Perencanaan Ketahanan Gempa Untuk Struktur Bangunan Gedung dan Nongedung. Jakarta: Badan Standardisasi Nasional.
- [BSN] Badan Standardisasi Nasional. (2020). SNI 1727-2020 Beban Minimum Pada Bangunan dan Struktur Lain. Jakarta: Badan Standardisasi Nasional.
- Achs, G., & Adam, C. (2012). A Rapid-Visual-Screening Methodology for the Seismic Vulnerability Assessment of Historic Brick-Masonry Buildings in Vienna. *15th World Conference on Earthquake Engineering (15WCEE)*, 154(2002).
- Adhyarini, Y. Z. (2021). 'Evaluasi Kegempaan Pada Bangunan Gedung Fakultas Teknik Universitas Jenderal Soedirman dengan Rapid Visual Screening'. Skripsi. Jurusan Teknik Sipil. Universitas Jenderal Soedirman. Purwokerto.
- Agustin, S., Djauhari, Z., & Suryanita, R. (2020). Aplikasi Metode Rapid Visual Screening (RVS) Dalam Monitoring Kerentanan Bangunan Pemerintahan di Indragiri Hulu. *Jurnal Rekayasa Sipil (JRS-Unand)*, 16(1), 38. <https://doi.org/10.25077/jrs.16.1.38-48.2020>
- Alfidiah, E. (2018). 'Evaluasi Kerentanan Gempa Pada Bangunan Gedung Laboratorium Fakultas Ekonomi dan Bisnis Universitas Jenderal Soedirman'. Skripsi. Jurusan Teknik Sipil. Universitas Jenderal Soedirman. Purwokerto.
- Astuti, N. D., Alvita, M. A., Sangadji, S., Rahmadi, A. P., & Purwanto, E. (2017). Rapid and in-depth analysis for seismic risk evaluation. *Journal of Physics: Conference Series*, 909(1). <https://doi.org/10.1088/1742-6596/909/1/012071>
- ATC. (2002). *Rapid Visual Screening of Buildings for Potential Seismic Hazards: A Handbook (2nd edition)*, prepared by the Applied Technology Council for the Federal Emergency Management Agency. FEMA 154 Report. Washington D.C.
- ATC. (2002b). *Rapid Visual Screening of Buildings Potential Seismic Hazards: Supporting Documentation*, prepared by the Applied Technology Council for the Federal Emergency Management Agency. FEMA 155 2nd Ed. Redwood.
- Birawaputra, I., & Tethool, Y. C. V. (2019). Penggunaan Metode Rapid Visual Screening Dalam Menentukan Kerentanan Bangunan Akibat Gempa Bumi. *INTAN Jurnal Penelitian Tambang*, 2(2), 97–105.
- Clemente, S. J. C., Arreza, J. S. B., Cortez, M. A. M., Imperial, J. R. C., & Malabanan, M. J. F. (2020). Risk Assessment of Seismic Vulnerability of All Hospitals in Manila Using Rapid Visual Screening (RVS). *IOP Conference Series: Earth and Environmental Science*, 479(1). <https://doi.org/10.1088/1755-1315/479/1/012002>
- Departemen PU Dirjen Cipta Kerja. (2006). *Pedoman Teknis Rumah dan Bangunan Gedung Tahan Gempa*. Departemen Pekerjaan Umum. Indonesia.
- Departemen Pekerjaan Umum. (1983). *Peraturan Pembebanan Indonesia Untuk Bangunan Gedung (PPIUG 1983)*. Bandung.

- Gunari, A. S. A. (2021). 'Evaluasi Kerentanan Gempa Pada Gedung Layanan Pembelajaran Fakultas Ilmu Sosial dan Politik Universitas Jenderal Soedirman dengan Metode Tier 1 FEMA 310'. Skripsi. Jurusan Teknik Sipil. Universitas Jenderal Soedirman. Purwokerto.
- FEMA P-154. (2015). *Handbook for Rapid Visual Screening of Buildings for Potential Seismic Hazards*. Federal Emergency Management Agency.
- Firdaus, R., Kurniawandy, A., Djauhari, Z. (2016). EVALUASI KERENTANAN BANGUNAN GEDUNG TERHADAP GEMPA BUMI DENGAN RAPID VISUAL SCREENING (RVS) BERDASARKAN FEMAP 154. *Jom FTEKNIK*, 3(2), 1.
- Fitriana, H. (2021). 'Evaluasi Kerentanan Gempa Pada Bangunan Gedung Fakultas Ilmu Sosial dan Ilmu Politik Universitas Jenderal Soedirman dengan Metode Rapid Visual Screening'. Skripsi. Jurusan Teknik Sipil. Universitas Jenderal Soedirman. Purwokerto.
- Harirchian, E., Lahmer, T., Buddhiraju, S., Mohammad, K., & Mosavi, A. (2020). Earthquake safety assessment of buildings through rapid visual screening. *Buildings*, 10(3), 1–15. <https://doi.org/10.3390/buildings10030051>
- Haryanto, Y., Hu, H.-T., Han, A. L., Hidayat, B. A., Widyaningrum, A., & Yulianita, P. E. (2020). Seismic Vulnerability Assessment Using Rapid Visual Screening: Case Study of Educational Facility Buildings of Jenderal Soedirman University, Indonesia. *Civil Engineering Dimension*, 22(1), 13–21. <https://doi.org/10.9744/ced.22.1.13-21>
- Haryanto, Y., Hu, H. T., Widyaningrum, A., Alfidiah, E., & Hidayat, B. A. (2020). FEMA 310 Tier 1 seismic evaluation of existing building: A case study of a 7-story academic RC building of Jenderal Soedirman University, Indonesia. *IOP Conference Series: Materials Science and Engineering*, 982(1). <https://doi.org/10.1088/1757-899X/982/1/012031>
- Joshi, G. C., & Kumar, R. (2010). Preliminary seismic vulnerability assessment of Mussoorie Town, Uttarakhand (India). *Journal of Building Appraisal*, 5(4), 357–368. <https://doi.org/10.1057/jba.2010.7>
- Karbassi, A., & Nollet, M. J. (2007). The adaptation of the FEMA 154 methodology for the rapid visual screening of existing buildings in accordance with NBCC-2005. *Ninth Canadian Conference on Earthquake Engineering, June*, 542–551.
- Khan, S. U., Qureshi, M. I., Rana, I. A., & Maqsoom, A. (2019). Seismic vulnerability assessment of building stock of Malakand (Pakistan) using FEMA P-154 method. *SN Applied Sciences*, 1(12), 1–14. <https://doi.org/10.1007/s42452-019-1681-z>
- Lizundia, B., Durphy, S., Griffin, M., Hortacsu, A., Kehoe, B., Porter, K., & Welliver, B. (2014). Rapid visual screening of buildings for potential seismic hazards: FEMA 154 and FEMA 155 updates. *NCEE 2014 - 10th U.S. National Conference on Earthquake Engineering: Frontiers of Earthquake Engineering, January*. <https://doi.org/10.4231/D3M90238V>
- Manik, K. M. (2021). 'Evaluasi Kerentanan Gempa Pada Bangunan Gedung Dekanat Fakultas Teknik Universitas Jenderal Soedirman dengan Metode Screening

Phase (Tier 1)'. Skripsi. Jurusan Teknik Sipil. Universitas Jenderal Soedirman. Purwokerto.

Mukhlis, M. R., Tangina, S. A., Mostazid, M. I., & Hoque, M. R. (2018). *Seismic Vulnerability Assessment of Existing Buildings in Chittagong City: a Case Study on Rampur Ward*. *Icrice*, 12–13.

Suwandono, J.E. (2017). *'Modifikasi Struktur Gedung Perkantoran MNC Surabaya dengan Menggunakan Metode Sistem Rangka Pemikul Momen Khusus (SRPMK) dan Metode Pelaksanaan Basement'*. Skripsi. Departemen Teknik Infrastruktur Sipil. Institut Teknologi Sepuluh Nopember. Surabaya.

Wahyuni, E., Aji, P., & Budi, F. (2017). Study of Rapid Visual Screening of Buildings for High Potential Seismic Hazard According to Indonesian Standard. *IPTEK Journal of Proceedings Series*, 0(2), 19. <https://doi.org/10.12962/j23546026.y2017i2.2273>

Zamzami, A. Y. (2020). *Penelitian Kerentanan Bangunan Gedung Terhadap Gempa Bumi dengan Metode Rapid Visual Screening (RVS)*. 67.

Zulfiar, M. H., Jayady, A., & Jati Saputra, N. R. (2018). Kerentanan Bangunan Rumah Cagar Budaya Terhadap Gempa Di Yogyakarta. *Jurnal Karkasa*, 4(1), 5. <https://doi.org/10.32531/jkar.v4i1.67>

<http://www.usgs.gov> (diakses pada 14 Agustus 2021 pukul 10.00)

<http://architectaria.com/tipe-tipe-cladding-atau-siding-yang-paling-populer.html> (diakses 6 September 2021 pukul 13.15)

<http://www.google.com> (diakses pada tanggal 10 September 2021 pukul 17.05)

<http://pdc.id> (diakses pada tanggal 28 Oktober 2021 pukul 15.42)

<http://www.perencanaanstruktur.com/2015/07/kelebihan-software-etabs-daripada-sap.html> (diakses 9 Desember 2021 pukul 11.28)

(Achs & Adam, 2012; Agustin et al., 2020; Astuti et al., 2017; Birawaputra & Tethool, 2019; Clemente et al., 2020; Harirchian et al., 2020; Haryanto, Hu, Han, et al., 2020; Haryanto, Hu, Widyaningrum, et al., 2020; Joshi & Kumar, 2010; Karbassi & Nollet, 2007; Khan et al., 2019; Lizundia et al., 2014; Mukhlis et al., 2018; Rapid et al., 2016; Sipil, 2015; Zamzami, 2020; Zulfiar et al., 2018)