

RINGKASAN

ANALISIS KOORDINASI KERJA PMT (PEMUTUS TENAGA) DENGAN RECLOSER AKIBAT GANGGUAN ARUS HUBUNG SINGKAT PADA PENYULANG KSN-12 GARDU INDUK KEBASEN PT. PLN (PERSERO) AREA TEGAL

Suprihatin

Energi listrik pada saat ini menjadi kebutuhan yang sangat penting baik untuk konsumen rumah tangga, maupun perusahaan. Pelayanan yang ramah, bersih dan bebas dari rugi-rugi (*losses*), serta handal dalam berbagai situasi wajib diutamakan PT. PLN (Persero) selaku perusahaan yang menyediakan energi listrik nasional. Untuk menjaga sebuah sistem yang handal, terutama dalam menangani gangguan listrik, maka peran peralatan proteksi dengan koordinasi yang baik menjadi hal yang sangat penting. Pada penyulang KSN-12, peralatan proteksi utama yang dipasang yaitu PMT (Pemutus Tenaga) dan *recloser*, dimana keduanya bekerja secara koordinatif dengan peralatan proteksi cadangan di masing-masing zonanya. Menurut data dari PT. PLN (Persero) Area Tegal, frekuensi terjadinya gangguan di penyulang KSN-12 cukup tinggi. Hal itu diindikasikan dengan tripnya PMT (Pemutus Tenaga) dan *recloser* dalam jangka waktu setahun terakhir (2015-2017) mencapai angka 24 kali dengan rata-rata durasi padam mencapai 30-60 menit. Analisis koordinasi proteksi ini dilakukan untuk menguji seberapa baik peralatan proteksi yang terpasang di penyulang KSN-12 dalam menangani gangguan arus hubung singkat melalui perbandingan data di lapangan, perhitungan teoritis, serta simulasi menggunakan *software* ETAP12.6.0. Sehingga diharapkan menghasilkan pengaturan (*setting*) terbaik untuk mengoptimalkan kinerja dari PMT (Pemutus Tenaga) dan *recloser* di penyulang KSN-12 dalam menangani gangguan listrik.

Kata kunci: Koordinasi proteksi, Peralatan proteksi

SUMMARY

ANALYSIS OF WORKING COORDINATION PMT(REPRESENTATIVES) WITH RECLOSE CONSEQUENT DISEASE FLOW CONTROL ON KSN-12 GARDU PARK KEBASEN PT. PLN (PERSERO) AREA TEGAL

Suprihatin

Electrical energy nowadays has already been a main need for all customers. A friendly service, clean, free from losses, and reliable in many situation must be underlined by PT. PLN (persero) as the company which provide national electrical energy. In order to keep a reliability of system, especially in solving electrical interupt, protection tools's role with its good coordination is the most important one. In KSN-12 feeder, PMT and recloser is the main protection tool which is used in. Both of it have operation principle that have to be synchronized to alternative protection tool in each zone. Based on PT. PLN (Persero) Purwokerto Area 'data, a number of interupt in KSN-12 feeder is very high. That's showed by PMT and recloser's operation frequency within last one year (2015-2017). It is about 30-60 minutes in which has reached about 24 times of average blackout duration. Basically, analysis for protection coordination itself is the kind of step to check how reliable its protection tool which is implemented in Kalibakal-10 feeder that is used to solve interupt such as short circuit condition. It's done by comparing between real data, teoritically calculation, and simulation using software ETAP12.6.0. Therefore, researcher totally believe that its analysis can produce the best setting or adjustment to optimalize the performance of PMT and recloser in KSN-12 feeder.

Keywords: Protection coordinati, Protection tool